M1943
FIELD TABLE
DIMENSIONS

3'

2' 10"

2'

5"

4"

1' 7"

2' 3"

1' 11"

6"

2' 7"

1' 7"

1' 11"

Bolt is locked
down in cut on
leg member stretcher
using wing nut & washer

Bolt is
welded into
"U" Bar

"U" bar is bolted through leg
support bar which is hinged to
table top